Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC. **Well Name:** WAYZETTA 100-26 SWD

Field Name: PARSHALL Well File #: 16733

Date Incident: 7/30/2015 Time Incident: 09:00 Facility ID Number:

County: MOUNTRAIL Twp: 153 Rng: 90 Sec: 26 Qtr: SW NE

Location Description:

Submitted By: Danielle Dupay Received By:

Contact Person: Danielle Dupay

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 10 Barrels 10 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

The release is contained onsite. In the line leak area tank area 10 bbls were evacuated and the line is being replaced. Several other daylighting monitoring holes have been place onsite to deliniate areas away from the leak. All daylighting holes will be monitored and more information and any other evacuation fluid amounts are TBD and will be included in the NDIC followup report.

Wastes Disposal Location: Liquids will be taken to SWD, Solids will be taken to Clean Harbors

Agencies Involved:

Updates

Date: 7/31/2015 Status: Reviewed - Assigned to Other Agency Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The release was contained within and E&P well pad. Oil & Gas retains oversight.